DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/19/2016 FORM APPROVED OMB NO. 0938-0391

	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
15G719		B. WING			04/12/2016	
NAME OF PROVIDER OR SUPPLIER REM-INDIANA INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1406 W TARKINGTON DR GREENSBURG, IN 47240			
SUMMARY STATEMENT OF DEFICIENCIES ((EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PREFIX (EACH CORRECTIVE ACTION SHOU			(X5) COMPLETION DATE
INITIAL COMMENTS		K 000				
A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).						
Survey Date: 04/12/16						
Facility Number: 004375 Provider Number: 15G719 AIM Number: 200510170						
At this Life Safety Code survey, Rem-Indiana Inc was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies.						
facility has a fire alarm detection in the corrid and hard wired smoke sleeping rooms. The	n system with smoke ors, common living areas, e detectors in all client facility has a capacity of 4					
Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 1.72.						
Quality Review comp	leted on 04/18/16 - DA					
	SUMMARY STA (EACH DEFICIENCY REGULATORY OR LE INITIAL COMMENTS A Life Safety Code R conducted by the Indi Health in accordance Survey Date: 04/12/1 Facility Number: 004 Provider Number: 15 AIM Number: 200510 At this Life Safety Code was found in compliant Participation in Medica 483.470(j), Life Safety edition of the National (NFPA) 101, Life Safety edition of the National (NFPA) 101, Life Safety edition of the National (NFPA) 101, Life Safety edition in the corridation of the Evaluation of the Evalu	ROVIDER OR SUPPLIER ANA INC SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) INITIAL COMMENTS A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/12/16 Facility Number: 004375 Provider Number: 15G719 AIM Number: 200510170 At this Life Safety Code survey, Rem-Indiana Inc was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies. This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, common living areas, and hard wired smoke detectors in all client sleeping rooms. The facility has a capacity of 4 and had a census of 3 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the	ROVIDER OR SUPPLIER ANA INC SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) INITIAL COMMENTS A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/12/16 Facility Number: 004375 Provider Number: 15G719 AIM Number: 200510170 At this Life Safety Code survey, Rem-Indiana Inc was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies. This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, common living areas, and hard wired smoke detectors in all client sleeping rooms. The facility has a capacity of 4 and had a census of 3 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 1.72.	TIDENTIFICATION NUMBER: A BUILDING I B. WING	TOENTIFICATION NUMBER: 15G719 15G719 15G719 15 B. WING SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY PULL REGULATORY OR LSC IDENTIFYING INFORMATION) INITIAL COMMENTS A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/12/16 Facility Number: 200510170 At this Life Safety Code survey, Rem-Indiana Inc was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety From Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies. This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, common living areas, and hard wired smoke detectors in all client sleeping rooms. The facility has a capacity of 4 and had a census of 3 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 1.72.	TOWNER OR SUPPLIER ANA INC SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC DENTIFYING INFORMATION) A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/12/16 Facility Number: 004375 Provider Number: 1563719 Alt his Life Safety Code survey, Rem-Indiana Inc was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies. This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, common living areas, and hard wired smoke detectors in all cilent sleeping rooms. The facility has a capacity of 4 and had a census of 3 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 1.72.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.